



PROCESS REQUIREMENTS

Code: HFQ-7.1-P05


Date: 07/05/21

Edition: 01

Rev: 01

Page: 2 de 2

CERTIFICATION SCHEME WEB



* Corrective action plan (PAC): In the case of minor non-conformities the company requires a plan of corrective actions.

** Closure of non-conformities: For larger NCs the company must correct them and provide the corresponding evidence.